



Errata

NFPA 70®

National Electrical Code®

2026 Edition

Reference: 500.8(B)(2)

Errata No: 70-26-5

Code-Making Panel 14 and the National Electrical Code Correlating Committee note the following error in the 2026 edition of *NFPA 70®*, *National Electrical Code®*.

1. Correct the word “for” to read “or” in 500.8(B)(2) as follows:

(2) Equipment Application.

Equipment identified for a Division 1 location shall be permitted in a Division 2 location of the same class, group, and temperature class and shall comply with the requirements of 500.8(B)(2)(a) **for or** 500.8(B)(2)(b) as applicable.

(a) Intrinsically safe apparatus having a control drawing requiring the installation of associated apparatus for a Division 1 installation shall be permitted to be installed in a Division 2 location if the same associated apparatus is used for the Division 2 installation.

(b) Equipment required to be explosionproof shall incorporate seals in accordance with 501.15(A) or 501.15(D) when the wiring methods of 501.10(B) are employed.

Issue Date: October 23, 2026

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/docinfo)

Copyright © 2026 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION