



Tentative Interim Amendment

NFPA® 70®

National Electrical Code®

2023 Edition

Reference: 215.15

TIA 23-4

(SC 22-8-18 / TIA Log #1655)

Note: Text of the TIA was issued and approved for incorporation into the document prior to printing.

1. Revise paragraph 215.15 to read as follows:

215.15 Barriers. Barriers shall be placed such that no energized, uninsulated, ungrounded busbar or terminal is exposed to inadvertent contact by persons or maintenance equipment while servicing load terminations in panelboards, switchboards, switchgear, or motor control centers supplied by feeder taps in 240.21(B) or transformer secondary conductors in 240.21(C) when the disconnecting device, to which the tap conductors are terminated, is in the open position.

Issue Date: August 12, 2022

Effective Date: September 1, 2022

(Note: For further information on NFPA Codes and Standards, please see www.nfpa.org/docinfo)

Copyright © 2022 All Rights Reserved

NATIONAL FIRE PROTECTION ASSOCIATION