



Errata

NFPA 1960

Standard for Fire Hose Connections, Spray Nozzles, Manufacturer's Design of Fire Department Ground Ladders, Fire Hose, and Powered Rescue Tools

2024 Edition

Reference: 22.4.1.2, 22.4.7.5, 23.4.3.4, 23.4.4.9, and 24.5.1.2

Errata No: 1960-24-1

The Technical Committee on Fire Hose notes the following errors in the 2024 edition of NFPA 1960, *Standard for Fire Hose Connections, Spray Nozzles, Manufacturer's Design of Fire Department Ground Ladders, Fire Hose, and Powered Rescue Tools*.

1. *Correct paragraph 22.4.1.2 to read as follows:*

22.4.1.2 Handles and controls shall be located on the rescue tool to allow the rescue tool to be carried and operated by personnel wearing gloves that are certified as compliant with the glove requirements of NFPA-1970 1971.

2. *Correct paragraph 22.4.7.5 to read as follows:*

22.4.7.5 Handles and controls shall be located on the power unit to allow the power unit to be carried and operated by personnel wearing gloves that are certified as compliant with the glove requirements of NFPA-1970 1971.

3. *Correct paragraph 23.4.3.4 to read as follows:*

23.4.3.4 All couplers and quick-connect couplers shall be able to be connected and disconnected while wearing gloves that are certified as compliant with the glove requirements of NFPA-1970 1971.

4. *Correct paragraph 23.4.4.9 to read as follows:*

23.4.4.9 Control devices shall be operated while wearing gloves that are certified as compliant with the glove requirements of NFPA-1970 1971.

5. *Correct paragraph 24.5.1.2 to read as follows:*

24.5.1.2 Where provided, handles and controls shall be located on the strut to allow the strut to be carried and operated by personnel wearing gloves that are certified as compliant with the glove requirements of NFPA-1970 1971.

Issue Date: December 21, 2023

(Note: For current information about the NFPA Codes and Standards, please see www.nfpa.org/docinfo)

Copyright © 2023 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION